

Inspection Photos
Operator: BP America
Location/API #: 067-06727
Date: 10-16-2019



Photo 1. View of the project area from the northeastern edge facing center.



Photo 2. View of the western project area from the northwestern corner facing southward.



Photo 3. View of reference area vegetation north of the project area. Vegetation is comprised of greasewood and mixed native and non-native perennial grasses, as well as cheatgrass.