

Final Reclamation Inspection

October 17, 2019

Operator: SRC ENERGY INC- #10311

Location ID: 323075

Inspection Document #: 697500740

Weld County, CO

NESW Section 16 T6N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: STATE-HOPPE #16-2
Location ID: 323075



Photo 1. Photo taken from the tank battery location, facing South. No visual evidence of oil and gas equipment on location.

Inspection Photos
Location Name: STATE-HOPPE #16-2
Location ID: 323075



Photo 2. Photo taken from the well location, facing East. Unable to find evidence of oil and gas activities and/or disturbances. Well location appears reflective of reference crop areas.

Inspection Photos
Location Name: STATE-HOPPE #16-2
Location ID: 323075



Photo 3. Reference photo taken north of the well location, facing Northeast. See comments under Photo 2.

Inspection Photos
Location Name: STATE-HOPPE #16-2
Location ID: 323075



Photo 4. Reference photo taken south of the well location, facing Southeast. See comments under Photo 2.