

**Inspection Photos**  
**Location Name: Hotchkiss Water Storage Facility**  
**Facility ID: 421193**



**Pit Facility ID #454880 (Lower Pit).**



**Bird deterrent pennants being strung up during this inspection.**

**Inspection Photos**  
**Location Name: Hotchkiss Water Storage Facility**  
**Facility ID: 421193**



**Lower pit with netting removed.**



**Upper Pit Facility ID #454881 with netting retracted for the winter.**