

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402215393  
Receive Date:  
10/21/2019

Report taken by:  
Candice (Nikki) Graber

Site Investigation and Remediation Workplan (Initial Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: <u>PDC ENERGY INC</u>	Operator No: <u>69175</u>	<b>Phone Numbers</b> Phone: <u>(303) 860-5800</u> Mobile: <u>( )</u>
Address: <u>1775 SHERMAN STREET - STE 3000</u>		
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80203</u>		
Contact Person: <u>Karen Olson</u> Email: <u>COGCCSpillRemediation@pdce.com</u>		

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 14462 Initial Form 27 Document #: 402215393

PURPOSE INFORMATION

- |  |  |
|--|--|
| <input type="checkbox"/> 901.e. Sensitive Area Determination                                       | <input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water                   |
| <input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure                             | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input checked="" type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation                 | <input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project                                  |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste                      | <input type="checkbox"/> Rule 906.c.: Director request   |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input type="checkbox"/> Other _____   |

SITE INFORMATION

N Multiple Facilities ( in accordance with Rule 909.c. )

Facility Type: <u>LOCATION</u>	Facility ID: <u>426637</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>Bosworth-Bailey 20-31</u>	Latitude: <u>40.525606</u>	Longitude: <u>-104.813738</u>	
	** correct Lat/Long if needed: Latitude: <u>40.525222</u>	Longitude: <u>-104.813655</u>	
QtrQtr: <u>SESE</u>	Sec: <u>31</u>	Twp: <u>7N</u>	Range: <u>66W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications SM Most Sensitive Adjacent Land Use Agriculture  
 Is domestic water well within 1/4 mile? Yes Is surface water within 1/4 mile? Yes  
 Is groundwater less than 20 feet below ground surface? Yes

Other Potential Receptors within 1/4 mile

Occupied housing is located approximately 320 feet east of the location. FWS wetlands are located approximately 752 feet east of the location. CPW Sensitive Wildlife Habitat (SWH) is located approximately 4,051 feet southwest of the location.

# SITE INVESTIGATION PLAN

## TYPE OF WASTE:

- |  |  |  |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste      | <input type="checkbox"/> Other E&P Waste             | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids             | _____                                  |
| <input type="checkbox"/> Oil                       | <input type="checkbox"/> Tank Bottoms                |  |
| <input type="checkbox"/> Condensate                | <input type="checkbox"/> Pigging Waste               |  |
| <input type="checkbox"/> Drilling Fluids           | <input type="checkbox"/> Rig Wash                    |  |
| <input type="checkbox"/> Drill Cuttings            | <input type="checkbox"/> Spent Filters               |  |
|  | <input type="checkbox"/> Pit Bottoms                 |  |
|  | <input type="checkbox"/> Other (as described by EPA) | _____                                  |

## DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	SOILS	Refer to Figure 1 and Table 1.	Confirmation Soil Sampling

## INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

On October 11, 2019, approximately 10 barrels of produced water were released into secondary containment at Bosworth-Bailey 9, 20-31 tank battery. Following the discovery, the well was shut in and mitigation activities were initiated.

## PROPOSED SAMPLING PLAN

### Proposed Soil Sampling

Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

On October 17, 2019, six soil samples (SS01 - SS06) were collected within the former release extent at approximately 6 inches below ground surface (bgs). The samples were submitted to Summit Scientific Laboratories in Golden, Colorado for analysis of benzene, toluene, ethylbenzene, total xylenes (BTEX), naphthalene, total petroleum hydrocarbons (TPH) - gasoline range organics (GRO) by EPA Method 8260B, TPH - diesel range organics (DRO) by EPA Method 8015, electrical conductivity (EC) by EPA Method 120.1, and pH by EPA Method 9045D. Analytical results indicated that pH was in exceedance of the applicable COGCC Table 910-1 standard in soil samples SS01, SS04, and SS05. In addition, soil sample SS04 exhibited a TPH concentration above the applicable regulatory standard. The remaining three soil samples exhibited constituent concentrations below regulatory standards. Soil analytical results are summarized in Table 1 and the release extent and sample locations are illustrated on Figure 1.

### Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

### Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

## Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

Based on the analytical results collected during the initial site investigation, hydrocarbon impacts in exceedance of regulatory standards remain within secondary containment. Confirmation soil samples will be collected following the completion of remediation activities.

# SITE INVESTIGATION REPORT

## SAMPLE SUMMARY

### Soil

Number of soil samples collected 6

Number of soil samples exceeding 910-1 3

Was the areal and vertical extent of soil contamination delineated? No

Approximate areal extent (square feet) 300

### NA / ND

--          Highest concentration of TPH (mg/kg) 680

NA          Highest concentration of SAR         

BTEX > 910-1 No

Vertical Extent > 910-1 (in feet) 0

### Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet)         

Number of groundwater monitoring wells installed         

Number of groundwater samples exceeding 910-1         

         Highest concentration of Benzene (µg/l)         

         Highest concentration of Toluene (µg/l)         

         Highest concentration of Ethylbenzene (µg/l)         

         Highest concentration of Xylene (µg/l)         

         Highest concentration of Methane (mg/l)         

### Surface Water

0 Number of surface water samples collected

         Number of surface water samples exceeding 910-1

If surface water is impacted, other agency notification may be required.

## OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) 3

Volume of liquid waste (barrels) 4

Is further site investigation required?

A site assessment will be conducted within secondary containment following bioremediation activities. Soil samples will be collected in the locations of the former soil samples (SS01, SS04, and SS05) which exhibited TPH and pH concentrations in exceedance of COGCC standards.

# REMEDIAL ACTION PLAN

## SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Remaining hydrocarbon impacted material will be treated in place with bioremediation amendments.

## REMEDICATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Bioremediation amendments will be applied to the entire release area within secondary containment. A post-remediation site assessment will be conducted to confirm that remaining impacts were successfully addressed. Remediation options may be evaluated upon receipt of assessment data.

## Soil Remediation Summary

### In Situ

- \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )
- \_\_\_\_\_ Chemical oxidation
- \_\_\_\_\_ Air sparge / Soil vapor extraction
- \_\_\_\_\_ Natural Attenuation
- \_\_\_\_\_ Other \_\_\_\_\_

### Ex Situ

- \_\_\_\_\_ Excavate and offsite disposal
- \_\_\_\_\_ If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_
- \_\_\_\_\_ Name of Licensed Disposal Facility or COGCC Facility ID # \_\_\_\_\_
- \_\_\_\_\_ Excavate and onsite remediation
- \_\_\_\_\_ Land Treatment
- \_\_\_\_\_ Bioremediation (or enhanced bioremediation)
- \_\_\_\_\_ Chemical oxidation
- \_\_\_\_\_ Other \_\_\_\_\_

## Groundwater Remediation Summary

- \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )
- \_\_\_\_\_ Chemical oxidation
- \_\_\_\_\_ Air sparge / Soil vapor extraction
- \_\_\_\_\_ Natural Attenuation
- \_\_\_\_\_ Other \_\_\_\_\_

## GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

# REMEDIATION PROGRESS UPDATE

## PERIODIC REPORTING

Frequency:  Quarterly  Semi-Annually  Annually  Other \_\_\_\_\_

Report Type:  Groundwater Monitoring  Land Treatment Progress Report  O&M Report

Other \_\_\_\_\_

## WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

No beneficial use.

Volume of E&P Waste (solid) in cubic yards \_\_\_\_\_ 3

E&P waste (solid) description E&P contaminated soil.

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: North Weld Waste Management Facility

Volume of E&P Waste (liquid) in barrels \_\_\_\_\_ 4

E&P waste (liquid) description Produced water.

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: NGL Energy Disposal Facility

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Following remediation and confirmation soil sampling, the affected area will be re-graded to match pre-existing conditions.

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim?  Final?

Did the Surface Owner approve the seed mix? \_\_\_\_\_

If NO, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

## IMPLEMENTATION SCHEDULE

### PRIOR DATES

Date of Surface Owner notification/consultation, if required. \_\_\_\_\_

Actual Spill or Release date, if known. 10/11/2019

### SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 10/11/2019

Date of commencement of Site Investigation. 10/17/2019

Date of completion of Site Investigation. \_\_\_\_\_

### REMEDIAL ACTION DATES

Date of commencement of Remediation. 10/11/2019

Date of completion of Remediation. \_\_\_\_\_

### SITE RECLAMATION DATES

Date of commencement of Reclamation. \_\_\_\_\_

Date of completion of Reclamation. \_\_\_\_\_

### OPERATOR COMMENT

A post-remediation site assessment will be conducted by May 1, 2020, and results will be summarized in Supplemental Form 27.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Karen Olson

Title: Senior Program Manager

Submit Date: 10/21/2019

Email: COGCCSpillRemediation@pdce.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Candice (Nikki) Graber

Date: 10/22/2019

Remediation Project Number: 14462

### COA Type

### Description

	On the Form 27 Supplemental Report, specify the amount (volume or mass) and name brand of the amendment added to the excavation. Attach the SDS for any additives applied to the excavation or injected at the site.
--	--

### Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

#### Att Doc Num

#### Name

402215393	FORM 27-INITIAL-SUBMITTED
402215528	ANALYTICAL RESULTS
402215959	SOIL SAMPLE LOCATION MAP

Total Attach: 3 Files

### General Comments

#### User Group

#### Comment

#### Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)