

Inspection Photos

Location Name: ROTHE-65N63W /29SWSW

Location #: 306702



Colorado Oil & Gas Conservation Commission
40.36508, -104.46726, 1379.0m, 58°
10/22/2019 04:13:08 PM

Photo #1

Rothe 14-29U (05-123-25134) Wellsite

Shut-In | SI



Colorado Oil & Gas Conservation Commission
40.36633, -104.46429, 1371.0m, 223°
10/22/2019 04:39:31 PM

Photo #2

Rothe 29BU, 13-29U, 14-29U, 23-29U, 24-29U Battery

Active