

Inspection Photos

Location Name:

API#: 05-071-

INSP. #: 695101



Colorado Oil & Gas Conservation Commission
37.21406, -104.70133, 2128.0m, 67°
2019/10/23 11:58:50

PHOTO 1: LOCATION



Colorado Oil & Gas Conservation Commission
37.21403, -104.70082, 2158.0m, 110°
2019/10/23 12:01:31

PHOTO 2: WELL SIGN



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: MANWAY 13-32 FOLLOWUP
API#: 05-071-06371
INSP. #: 695101580



PHOTO 3: Inadequate berms around tank. Repair or install berms or other secondary containment devices per Rule 605.a.(4). CA DATE 11-23-19.

PHOTO 4: THIS TANK DOES NOT APPEAR TO BEING PLUMBED IN OR IN USE. UNUSED EQUIPMENT. REMOVE UNUSED EQUIPMENTN PER RULE 603.f. CA DATE 11-23-19.