

Inspection Photos
Operator: BP America
Location/API #: 067-09445
Date: 10-16-2019



Photo 1. View of the project area from the southeastern project area facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Vegetation is well established, and comprised largely with perennial grasses such as western wheatgrass, crested wheatgrass, and smooth brome.



Photo 3. View of reference area vegetation comprised of sagebrush, rubber rabbitbrush, and perennial grasses and forbs representative of the sagebrush shrubland vegetation type.