

Inspection Photos
Location Name: HSR Teets #3-29A
Location ID: 331239



Photo #1 Access road



Photo #2 WH sign

Inspection Photos
Location Name: HSR Teets #3-29A
Location ID: 331239



Photo #3 Dead weeds around location

Photo #4 Dead weeds around location