

Inspection Photos

API: 05-071-07693

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/18/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07693 | Date: 10/18/2019

Inspection Photos



Photo 1. The main road has been regraded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07693 | Date: 10/18/2019

Inspection Photos



Photo 2. The culvert has been maintained along the road and the access road has been graded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07693 | Date: 10/18/2019

Inspection Photos



Photo 3. Rock rip/rap was installed along the rad near the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07693 | Date: 10/18/2019

Inspection Photos



Photo 4. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07693 | Date: 10/18/2019