

Inspection Photos
Location Name: Clark 11-27
Location ID: 305291



Colorado Oil and Gas Conservation Commission
40.55241, -104.65581, 1450.8m, 45°
Oct 24, 2019 10:12:12

Photo 1: Wellhead Sign



Colorado Oil and Gas Conservation Commission
40.5524, -104.65581, 1451.6m, 46°
Oct 24, 2019 10:12:20

Photo 2: Wellhead; Equipment removed

Inspection Photos
Location Name: Clark 11-27
Location ID: 305291



Photo 3: Centralized Tank Battery



Photo 4: Holes in berm repaired.

Inspection Photos
Location Name: Clark 11-27
Location ID: 305291



Photo 5: Equipment removed