Inspection Photos
Location Name: HSR-Guttersen “A” 9-3
Location ID: 329957

Photo #1 Wellhead & Sign

Photo #2 Variance Tag

Inspection Photos
Location Name: HSR-Guttersen “A” 9-3
Location ID: 329957

Photo #3 Weeds around ECD

Photo #4 Weeds around Separator

Inspection Photos
Location Name: HSR-Guttersen “A” 9-3
Location ID: 329957

Photo #5 Weeds around Meter Run/ Separator

Photo #6 Tank Battery & Weeds

Inspection Photos
Location Name: HSR-Guttersen “A” 9-3
Location ID: 329957

Photo #7 Weeds in Tank Battery

Photo #8 Weeds in Tank Battery

Inspection Photos
Location Name: HSR-Guttersen “A” 9-3
Location ID: 329957

Photo #9 Weeds in Tank Battery

Photo #10 Weeds in Tank Battery