

# *Inspection Photos*

*API#077-08087*

*Operator: Caerus*

*Inspection Number: 692401519*

*Inspection Date: 10/24/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to Northwest.

September 19, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus PA Wallace Currier API#077-08087



Photo#2:  
Overview of Location to West.

September 19, 2019