

Inspection Photos
Location Name: HSR-Lost Creek 16-29
Location ID: 465199



Photo 1 – Weeds at Separator



Photo 2 – Weeds at Tank Battery