

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/17/2019

Submitted Date:

10/25/2019

Document Number:

689703661

FIELD INSPECTION FORM

| | | | | |
|--|------------------------------------|---|-------------------|---|
| Loc ID 335901 | Inspector Name: LONGWORTH, MIKE | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ | Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 26 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested |
| Operator Information: OGCC Operator Number: 10456 Name of Operator: CAERUS PICEANCE LLC Address: 1001 17TH STREET #1600 City: DENVER State: CO Zip: 80202 | | | | ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE |

Contact Information:

| Contact Name | Phone | Email | Comment |
|-------------------|-------|---|---------------------------|
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| , Caerus Piceance | | COGCC.inspections@caerus oilandgas.com | Piceance inspections only |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------------|-------------|
| 297475 | WELL | PR | 10/05/2009 | GW | 045-16853 | N. PARACHUTE EF15B D19B 595 | PR |
| 297825 | WELL | PR | 10/13/2009 | GW | 045-16969 | N. PARACHUTE EF06C D19B 595 | PR |
| 297826 | WELL | PR | 11/01/2009 | GW | 045-16970 | N. PARACHUTE EF10D D19B 595 | PR |
| 297827 | WELL | PR | 10/04/2009 | GW | 045-16971 | N. PARACHUTE EF14C D19B 595 | PR |
| 297828 | WELL | PR | 11/01/2009 | GW | 045-16972 | N. PARACHUTE EF07D D19B 595 | PR |
| 297829 | WELL | PR | 11/01/2009 | GW | 045-16973 | N. PARACHUTE EF06D D19B 595 | PR |
| 297830 | WELL | PR | 11/01/2009 | GW | 045-16974 | N. PARACHUTE EF10C D19B 595 | PR |
| 297831 | WELL | PR | 11/01/2009 | GW | 045-16975 | N. PARACHUTE EF10B D19B 595 | PR |
| 297833 | WELL | PR | 11/01/2009 | GW | 045-16976 | N. PARACHUTE EF10A D19B 595 | PR |
| 297834 | WELL | PR | 10/04/2009 | GW | 045-16977 | N. PARACHUTE EF14A D19B 595 | PR |
| 297836 | WELL | PR | 10/04/2009 | GW | 045-16978 | N. PARACHUTE EF15A D19B 595 | PR |
| 297837 | WELL | PR | 07/01/2018 | GW | 045-16979 | N. PARACHUTE EF08C D19B 595 | PR |
| 297838 | WELL | PR | 12/01/2009 | GW | 045-16980 | N. PARACHUTE EF08B D19B 595 | PR |

| | | | | | | | |
|--------|------|----|------------|----|-----------|--------------------------------|----|
| 297839 | WELL | PR | 12/01/2009 | GW | 045-16981 | N. PARACHUTE EF03D D19B 595 | PR |
| 297840 | WELL | PR | 12/01/2009 | GW | 045-16982 | N. PARACHUTE EF02D D19B 595 | PR |
| 297841 | WELL | PR | 06/06/2008 | GW | 045-16983 | N. PARACHUTE EF04B D19B 595 | PR |
| 297842 | WELL | PR | 11/01/2009 | GW | 045-16984 | N. PARACHUTE EF06A D19B 595 | PR |
| 298923 | WELL | PR | 10/25/2009 | GW | 045-17475 | N. PARACHUTE EF11B D19B 595 | PR |
| 298924 | WELL | PR | 10/04/2009 | GW | 045-17476 | N. PARACHUTE EF11C D19B 595 | PR |
| 298925 | WELL | PR | 09/29/2009 | GW | 045-17477 | N. PARACHUTE EF14B D19B 595 | PR |
| 298926 | WELL | PR | 12/01/2009 | GW | 045-17478 | N. PARACHUTE EF07B D19B 595 | PR |
| 298927 | WELL | PR | 10/03/2009 | GW | 045-17479 | N. PARACHUTE EF11D D19B 595 | PR |
| 298928 | WELL | PR | 12/01/2009 | GW | 045-17480 | N. PARACHUTE EP07C D19B 595 | PR |
| 298936 | WELL | PR | 10/04/2009 | GW | 045-17481 | N. PARACHUTE EF11A D19B 595 | PR |

General Comment:[Follow Up Field inspection](#)

On 10/17/2019, I, Inspector Mike Longworth, conducted a follow up field inspection at CAERUS PICEANCE LLC N. PARACHUTE-65S95W 19LOT 2, at Location # 335901 in Garfield County, Colorado

All corrective actions have been addressed from 09/10/2019 Inspection # 689703523

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action: | | Date: | |

Overall Good: ☒

| | | | |
|----------------------|------------|-------|--|
| Signs/Marker: | | | |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 911 Added to battery sign

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|-------|-------|--|
| Type | TRASH | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good: ☒

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 297475 | Type: | WELL | API Number: | 045-16853 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 297825 | Type: | WELL | API Number: | 045-16969 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 297826 | Type: | WELL | API Number: | 045-16970 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 297827 | Type: | WELL | API Number: | 045-16971 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 297828 | Type: | WELL | API Number: | 045-16972 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 297829 | Type: | WELL | API Number: | 045-16973 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 297830 | Type: | WELL | API Number: | 045-16974 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 297831 | Type: | WELL | API Number: | 045-16975 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

| | | | | | | | | | |
|------------------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 297833 | Type: | WELL | API Number: | 045-16976 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 297834 | Type: | WELL | API Number: | 045-16977 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 297836 | Type: | WELL | API Number: | 045-16978 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 297837 | Type: | WELL | API Number: | 045-16979 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 297838 | Type: | WELL | API Number: | 045-16980 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 297839 | Type: | WELL | API Number: | 045-16981 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 297840 | Type: | WELL | API Number: | 045-16982 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 297841 | Type: | WELL | API Number: | 045-16983 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

| | | | | | | | | | |
|------------------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 297842 | Type: | WELL | API Number: | 045-16984 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 298923 | Type: | WELL | API Number: | 045-17475 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 298924 | Type: | WELL | API Number: | 045-17476 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 298925 | Type: | WELL | API Number: | 045-17477 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 298926 | Type: | WELL | API Number: | 045-17478 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 298927 | Type: | WELL | API Number: | 045-17479 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 298928 | Type: | WELL | API Number: | 045-17480 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 298936 | Type: | WELL | API Number: | 045-17481 | Status: | PR | Insp. Status: | PR |
| <u>Producing Well</u> | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------------|---|
| 689703678 | Inspectio 689703661 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4972659 |