

Inspection Photos

API: 05-071-08103

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/18/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08103 | Date: 10/18/2019

Inspection Photos



Photo 1. Facing east toward the location. Vegetation has established at the location which consists of *Dac glo*, *Pas smi*, *Sch sco*, *Bro ine*, among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08103 | Date: 10/18/2019

Inspection Photos



Photo 2. Facing west at the location. Vegetation has established at the location which consists of Dac glo, Pas smi, Sch sco, Bro ine, among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08103 | Date: 10/18/2019

Inspection Photos



Photo 3. The slopes at the location appear to be stabilized with vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08103 | Date: 10/18/2019

Inspection Photos



Photo 4. Facing southeast toward the location. Vegetation has established at the location which consists of *Dac glo*, *Pas smi*, *Sch sco*, *Bro ine*, among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08103 | Date: 10/18/2019