

Inspection Photos

API: 05-071-08948

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/18/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08948 | Date: 10/18/2019

Inspection Photos



Photo 1. Facing east toward the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08948 | Date: 10/18/2019

Inspection Photos



Photo 2. The culvert outlet and inlet were cleaned out of sediment buildup. Ditch has been excavated for stormwater drainage.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08948 | Date: 10/18/2019

Inspection Photos



Photo 3. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08948 | Date: 10/18/2019

Inspection Photos



Photo 4. Well sign has not been updated to reflect the current operator.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08948 | Date: 10/18/2019

Inspection Photos



Photo 5. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08948 | Date: 10/18/2019

Inspection Photos



Photo 6. The noxious weeds have been controlled, cut, and removed



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-08948 | Date: 10/18/2019