

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/17/2019

Submitted Date:

10/25/2019

Document Number:

689703661

FIELD INSPECTION FORM

Loc ID 335901 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

26 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297475	WELL	PR	10/05/2009	GW	045-16853	N. PARACHUTE EF15B D19B 595	PR
297825	WELL	PR	10/13/2009	GW	045-16969	N. PARACHUTE EF06C D19B 595	PR
297826	WELL	PR	11/01/2009	GW	045-16970	N. PARACHUTE EF10D D19B 595	PR
297827	WELL	PR	10/04/2009	GW	045-16971	N. PARACHUTE EF14C D19B 595	PR
297828	WELL	PR	11/01/2009	GW	045-16972	N. PARACHUTE EF07D D19B 595	PR
297829	WELL	PR	11/01/2009	GW	045-16973	N. PARACHUTE EF06D D19B 595	PR
297830	WELL	PR	11/01/2009	GW	045-16974	N. PARACHUTE EF10C D19B 595	PR
297831	WELL	PR	11/01/2009	GW	045-16975	N. PARACHUTE EF10B D19B 595	PR
297833	WELL	PR	11/01/2009	GW	045-16976	N. PARACHUTE EF10A D19B 595	PR
297834	WELL	PR	10/04/2009	GW	045-16977	N. PARACHUTE EF14A D19B 595	PR
297836	WELL	PR	10/04/2009	GW	045-16978	N. PARACHUTE EF15A D19B 595	PR
297837	WELL	PR	07/01/2018	GW	045-16979	N. PARACHUTE EF08C D19B 595	PR
297838	WELL	PR	12/01/2009	GW	045-16980	N. PARACHUTE EF08B D19B 595	PR

297839	WELL	PR	12/01/2009	GW	045-16981	N. PARACHUTE EF03D D19B 595	PR
297840	WELL	PR	12/01/2009	GW	045-16982	N. PARACHUTE EF02D D19B 595	PR
297841	WELL	PR	06/06/2008	GW	045-16983	N. PARACHUTE EF04B D19B 595	PR
297842	WELL	PR	11/01/2009	GW	045-16984	N. PARACHUTE EF06A D19B 595	PR
298923	WELL	PR	10/25/2009	GW	045-17475	N. PARACHUTE EF11B D19B 595	PR
298924	WELL	PR	10/04/2009	GW	045-17476	N. PARACHUTE EF11C D19B 595	PR
298925	WELL	PR	09/29/2009	GW	045-17477	N. PARACHUTE EF14B D19B 595	PR
298926	WELL	PR	12/01/2009	GW	045-17478	N. PARACHUTE EF07B D19B 595	PR
298927	WELL	PR	10/03/2009	GW	045-17479	N. PARACHUTE EF11D D19B 595	PR
298928	WELL	PR	12/01/2009	GW	045-17480	N. PARACHUTE EP07C D19B 595	PR
298936	WELL	PR	10/04/2009	GW	045-17481	N. PARACHUTE EF11A D19B 595	PR

General Comment:[Follow Up Field inspection](#)

On 10/17/2019, I, Inspector Mike Longworth, conducted a follow up field inspection at CAERUS PICEANCE LLC N. PARACHUTE-65S95W 19LOT 2, at Location # 335901 in Garfield County, Colorado

All corrective actions have been addressed from 09/10/2019 Inspection # 689703523

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911 Added to battery sign		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	TRASH		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	297475	Type:	WELL	API Number:	045-16853	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	297825	Type:	WELL	API Number:	045-16969	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	297826	Type:	WELL	API Number:	045-16970	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:					Date:				
Facility ID:	297827	Type:	WELL	API Number:	045-16971	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	297828	Type:	WELL	API Number:	045-16972	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	297829	Type:	WELL	API Number:	045-16973	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	297830	Type:	WELL	API Number:	045-16974	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	297831	Type:	WELL	API Number:	045-16975	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				

Facility ID: 297833	Type: WELL	API Number: 045-16976	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 297834	Type: WELL	API Number: 045-16977	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 297836	Type: WELL	API Number: 045-16978	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 297837	Type: WELL	API Number: 045-16979	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 297838	Type: WELL	API Number: 045-16980	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 297839	Type: WELL	API Number: 045-16981	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 297840	Type: WELL	API Number: 045-16982	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 297841	Type: WELL	API Number: 045-16983	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:

Facility ID: 297842	Type: WELL	API Number: 045-16984	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 298923	Type: WELL	API Number: 045-17475	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 298924	Type: WELL	API Number: 045-17476	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 298925	Type: WELL	API Number: 045-17477	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 298926	Type: WELL	API Number: 045-17478	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 298927	Type: WELL	API Number: 045-17479	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 298928	Type: WELL	API Number: 045-17480	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 298936	Type: WELL	API Number: 045-17481	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689703661	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4972661
689703678	Inspectio 689703661 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4972659