

Inspection Photos

Loc#335692

Operator: Caerus

Inspection Number: 692401509

Inspection Date: 10/15/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northeast.

October 15, 2019




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus N P Loc#335692



Photo#2:
View down steep fill slope.



Photo#3:
View off solar Panel maintenance ladder.

October 15, 2019




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus N P Loc#335692



Photo#4:
View across pad.



Photo#5:
Mine entry.

October 15, 2019