

Inspection Photos
Location Name: Ridgeview 32-16-1
Location ID: 430051



Photo 1. Ongoing leak at wellhead.



Photo 2. Ongoing leak at wellhead. Photo from 8/14/2019 inspection document number 689802979.



Inspection Photos
Location Name: Ridgeview 32-16-1
Location ID: 430051



Photo 3. Ongoing leak at tank flowline, water in photo is all from leak.



Photo 4. Ongoing leak at tank flowline. Photo from 8/14/2019 inspection document number 689802979.

Inspection Photos
Location Name: Ridgeview 32-16-1
Location ID: 430051



Photo 5. Ongoing leak at tank flowline, water in photo is all from leak.



Photo 6. Stained soil at separator.

