

Inspection Photos
Location Name: WARDLAW-66N64W /28SESE
Location #: 305111



Photo #1
Wardlaw 20-28 (05-123-22511) Wellsite
Temporarily Abandoned | TA
Unused Equipment needs removed
prior insp.



Photo #2
Wardlaw 20-28 (05-123-22511) Wellsite
Temporarily Abandoned | TA
Unused Equipment appears removed

Inspection Photos

Location Name: WARDLAW-66N64W /28SESE

Location #: 305111



Photo #3

Webster 15-28, Wardlaw 16-28, 20-28 Battery

Shut-down | Inactive



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources