

Inspection Photos
Operator: BP America
Location/API #: 067-06667
Date: 10-22-2019



Photo 1. View of the project area from the eastern edge facing center. Well head marker surrounded by fencing. Location is infested with approximately 1000 musk thistles. What appears to be surface owner equipment is stored in portions of the well pad.



Photo 2. View of tank that remains on the location. Unknown white material remains on the bottom of the tank.



Photo 3. View of riser that remains on the location.



Photo 4. View of another riser (orange and white) that remains on location.



Photo 5. View of bare and eroding cut-slope within the northern project area.



Photo 6. View of area in the northeastern project area where sediment flows off of the project area.



Photo 7. View of erosional channels in the northeastern fill slope, upstream from sediment deposition shown in Photo 6.



Photo 8. View of reference area comprised of mixed pinyon juniper woodland and sagebrush shrubland.