

Inspection Photos

Loc#311577

Operator: Caerus

Inspection Number: 692401530

Inspection Date: 10/25/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northwest.

October 25, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Federal Loc#31577



Photo#2:
Vegetation is successful and uniform in Interim areas



Photo#3:
Access road is Stable

October 25, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Federal Loc#31577