



99999999

075-40046

PVA?
WELL SITE INSPECTION

PERMIT NO 7

OPERATOR

Jaguar-Balderson

DATE

July 26 1985

WELL NAME

Condon 1

COUNTY

Logan

RIG

LEGAL

w/NES 22T9W R 50W

SURFACE CASING

SIZE

DEPTH

DATE

CEMENT VOLUME

RETURNS

WOC

PROBABLE FOX HILLS DEPTH

MUD PITS

DISPOSAL

PRODUCTION STRING

SIZE

DEPTH

STAGED

CBL CHECKED

SQUEEZE

FRAC JOB

BATTERY

SIGN

SITE INSPECTION AFTER DRILLING

No evidence of drill

site - only one path in pasture

around rolling pasture.

No flat places

DIRECTIONS

ACTION

ENGINEER

R. B. Snell



00800930

WELL SITE INSPECTION

072-40046

OPERATOR *John - Robinson*

WELL NAME *Cooper 1*

HIS _____

SURFACE CASING _____

CEMENT VOLUME _____

PROBABLE BOX HOLE DEPTH _____

MUD PITS _____

DISPOSAL _____

PRODUCTION _____

STAGED _____

SOURCES _____

BATTERY _____

SITE INSPECTION _____

DIRECTIONS _____

ACTION _____

ENGINEER *Rob C*

HAVE DENNIS FIELD
CHECK FOR STATUS
GAVE HIM AN OLD
COPY OF APPLIC
54- ONLY THING
IN FILE.
6-19-85

8-7-85

IT SOUNDS AS THOUGH THIS
WELL WAS NEVER DRILLED,
BUT WE DON'T KNOW THIS
FOR SURE. SO, LEAVE PLAT
AS IS, WITH THIS INFO IN
THE FILE.

Bob C

