

Inspection Photos

Well 081-07747

Inspection Date: 10/28/2019

Photos taken by Kris Neidel



Photo #1 sign at entry to location

Inspection Photos

Well 081-07747

Inspection Date: 10/28/2019

Photos taken by Kris Neidel



Photo #2 sign at wellhead, fence around wellhead.



Inspection Photos
Well 081-07747
Inspection Date: 10/28/2019
Photos taken by Kris Neidel

Photo #3 ongoing spill at wellhead



Inspection Photos
Well 081-07747
Inspection Date: 10/28/2019
Photos taken by Kris Neidel

Photo #4 Wellhead



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
Well 081-07747
Inspection Date: 10/28/2019
Photos taken by Kris Neidel

Photo #5 Wellhead, ongoing spill



Inspection Photos
Well 081-07747
Inspection Date: 10/28/2019
Photos taken by Kris Neidel

Photo #6 Wellhead, ongoing spill



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
Well 081-07747
Inspection Date: 10/28/2019
Photos taken by Kris Neidel

Photo #7 Wellhead, ongoing spill



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Well 081-07747

Inspection Date: 10/28/2019

Photos taken by Kris Neidel



Photo #8 ongoing spill at tank battery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
Well 081-07747
Inspection Date: 10/28/2019
Photos taken by Kris Neidel

Photo #9 ongoing spill at tank battery



Inspection Photos
Well 081-07747
Inspection Date: 10/28/2019
Photos taken by Kris Neidel

Photo #10 ongoing spill at tank battery



Inspection Photos
Well 081-07747
Inspection Date: 10/28/2019
Photos taken by Kris Neidel

Photo #11 ground below spill at tank flowline.

Inspection Photos

Well 081-07747

Inspection Date: 10/28/2019

Photos taken by Kris Neidel



Photo #12 sign at tankbattery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
Well 081-07747
Inspection Date: 10/28/2019
Photos taken by Kris Neidel

Photo #13 treater



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Well 081-07747

Inspection Date: 10/28/2019

Photos taken by Kris Neidel



Photo #14 Treater. The sight glass that had caused a spill previously has not been replaced.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Well 081-07747

Inspection Date: 10/28/2019

Photos taken by Kris Neidel



Photo #15 Flare Pit



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Well 081-07747

Inspection Date: 10/28/2019

Photos taken by Kris Neidel



Photo #16 close up of flare pit.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources