

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/25/2019

Submitted Date:

10/29/2019

Document Number:

697000121

FIELD INSPECTION FORM

Loc ID 303350 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 25255

Name of Operator: DUKE GAS COMPANY LLC

Address: 22500 COUNTY RD 24

City: VERNON State: CO Zip: 80755

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Cantrall, Diana		dcantrall@plainstel.corp	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252951	WELL	PR	06/01/2017	GW	125-06828	CANTRALL 2-35	PR

General Comment:

Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Dirt road through farm ground		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign for Cantrall 2-35 by meter shed		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	Gas scrubber at wellhead (for domestic use). Telemetry equipment at meter shed		
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:	Shared meter run for (Cantrall 35-1, 35-7, 35-8) 240' north of wellhead		
Corrective Action:		Date:	
Type: Vertical Separator	# 4		
Comment:	3-Vertical gas separators 50% buried by meter shed for the Cantrall 35-1, 35-7, 35-8 1-Vertical gas separator 50% buried by meter shed abandoned and not in use (for Cantrall 2-35)		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	252951	Type:	WELL	API Number:	125-06828	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well is SI at wellhead with meter run removed at meter shed. VGS is still in place at meter shed. Well is converted to domestic well for farmhouse. Central meter run for (Cantrall 35-1, 35-7, 35-8) 240' N of wellhead								
Corrective Action:	Submit Sundry notice for current well status (DM). Contact COGCC Flowline Intergrity Group for flowline registration. ellice.whittington@state.co.us							Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: Location and access are farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT