

Inspection Photos
API#045-12459
Operator: Terra
Inspection: #692401540
Inspection Date: 10/25/19





Photo#1:
Overview of Location to Northwest.

October 25, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra AL Chevron API#045-12459



Photo#2:
Start of Access road at point where departs from Lease road.

October 25, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra AL Chevron API#045-12459



Photo#3:
View along access road out of Location.



Photo#4:
View along access road into Location.

October 25, 2019