

Inspection Photos
Operator: BP America
Location/API #: 067-07521
Date: 10-22-2019



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern edge facing eastward. Vegetation is progressing in portions of the reclamation area, with grasses such as western wheatgrass and Indian ricegrass. Weeds such as musk thistles and kochia need to be controlled.



Photo 3. View of Kochia debris, up to 5 feet tall growing along the edge of the working area.



Photo 4. View of musk thistles growing within the southern project area.



Photo 5. View of reference area vegetation comprised of open grassland in a post-fire recovery condition, with burned trees and largely native grasses such as sand dropseed and forbs such as annual sunflower.