

Inspection Photos
Location Name: Tateyama 15U-434
Location ID: 432487



Photo 1: Tank Battery Sign



Photo 2: Location



Inspection Photos
Location Name: Tateyama 15U-434
Location ID: 432487



Photo 3: Risers removed



Photo 4: Separator not anchored

