



Inspection Photos

Well 081-07747

Inspection Date: 10/30/2019

Photos taken by Kris Neidel

Photo #1 wellhead



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Well 081-07747

Inspection Date: 10/30/2019

Photos taken by Kris Neidel



Photo #2 Ice at wellhead, ongoing spill.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Well 081-07747

Inspection Date: 10/30/2019

Photos taken by Kris Neidel



Photo #3 ongoing spill at tank battery

Inspection Photos

Well 081-07747

Inspection Date: 10/30/2019

Photos taken by Kris Neidel



Photo #4 spill at tank battery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources