

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402227394  
Receive Date:  
10/31/2019

Report taken by:  
Candice (Nikki) Graber

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATON

Name of Operator: SRC ENERGY INC	Operator No: 10311	<b>Phone Numbers</b>
Address: 1675 BROADWAY SUITE 2600		Phone: (970) 4755220
City: DENVER State: CO Zip: 80202		Mobile: ( )
Contact Person: Dave Castro	Email: dcastro@srcenergy.com	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 14290 Initial Form 27 Document #: 402195524

PURPOSE INFORMATION

- 901.e. Sensitive Area Determination
- 909.c.(1), Rule 905: Pit or PW vessel closure
- 909.c.(2), Rule 906: Spill/Release Remediation
- 909.c.(3), Rule 907.e.: Land treatment of oily waste
- 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure
- 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water
- Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b.
- Rule 909.e.(2)B.: Closure of remediation project
- Rule 906.c.: Director request
- Other

SITE INFORMATION

N Multiple Facilites ( in accordance with Rule 909.c. )

Facility Type: LOCATION	Facility ID: 328650	API #: _____	County Name: WELD
Facility Name: CAMENISCH-65N66W 33SWSE	Latitude: 40.350797	Longitude: -104.781709	
	** correct Lat/Long if needed: Latitude: 40.351066	Longitude: -104.780351	
QtrQtr: SWSE	Sec: 33	Twp: 5N	Range: 66W Meridian: 6 Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications SM Most Sensitive Adjacent Land Use irrigation ditch  
 Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? Yes  
 Is groundwater less than 20 feet below ground surface? Yes

Other Potential Receptors within 1/4 mile

Evans Town Ditch 110' north, Big Thompson River 60' south, inside 100yr floodplain, wetland 110' south

# SITE INVESTIGATION PLAN

## TYPE OF WASTE:

- |  |  |  |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste      | <input type="checkbox"/> Other E&P Waste             | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids             | _____                                  |
| <input type="checkbox"/> Oil                       | <input type="checkbox"/> Tank Bottoms                |  |
| <input type="checkbox"/> Condensate                | <input type="checkbox"/> Pigging Waste               |  |
| <input type="checkbox"/> Drilling Fluids           | <input type="checkbox"/> Rig Wash                    |  |
| <input type="checkbox"/> Drill Cuttings            | <input type="checkbox"/> Spent Filters               |  |
|  | <input type="checkbox"/> Pit Bottoms                 |  |
|  | <input type="checkbox"/> Other (as described by EPA) | _____                                  |

## DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
No	GROUNDWATER	0	sampling
No	SOILS	0	sampling

## INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

There is 1 partially buried produced water vault at the location that was removed.

## PROPOSED SAMPLING PLAN

### Proposed Soil Sampling

Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

The pit will have grab soil samples collected from the 4 cardinal directions 2.5' below the ground surface on the side walls, as well as from the pit bottom. The sidewall samples will be field screened in a 1-gallon clear plastic ziplock bag with a PID and the highest reading of the 4 will be sent to the lab for analysis, along with the pit bottom grab sample. Soil samples will be sent to Origins Laboratory in Denver for DRO/GRO/BTEX (sidewall and pit bottom) and EC/pH/SAR (sidewall only) analyses.

### Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

It is not anticipated that the bottom of the open pit left behind by the removal of the partially buried produced water vault will interact with groundwater. However, if it is found that is the case, a groundwater grab sample will be collected and submitted to Origins Laboratory for BTEX analysis.

### Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

\_\_\_\_\_

### Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

\_\_\_\_\_

# SITE INVESTIGATION REPORT

## SAMPLE SUMMARY

### Soil

Number of soil samples collected 2  
Number of soil samples exceeding 910-1 0  
Was the areal and vertical extent of soil contamination delineated? Yes  
Approximate areal extent (square feet) 0

### NA / ND

-- Highest concentration of TPH (mg/kg) 110.5  
-- Highest concentration of SAR 0.64  
BTEX > 910-1 No  
Vertical Extent > 910-1 (in feet) 0

### Groundwater

Number of groundwater samples collected 1  
Was extent of groundwater contaminated delineated? Yes  
Depth to groundwater (below ground surface, in feet) 5'  
Number of groundwater monitoring wells installed 0  
Number of groundwater samples exceeding 910-1 0

ND Highest concentration of Benzene (µg/l) \_\_\_\_\_  
-- Highest concentration of Toluene (µg/l) 4.27  
ND Highest concentration of Ethylbenzene (µg/l) \_\_\_\_\_  
-- Highest concentration of Xylene (µg/l) 15.2  
NA Highest concentration of Methane (mg/l) \_\_\_\_\_

### Surface Water

0 Number of surface water samples collected  
       Number of surface water samples exceeding 910-1  
If surface water is impacted, other agency notification may be required.

## OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) \_\_\_\_\_ Volume of liquid waste (barrels) \_\_\_\_\_

Is further site investigation required?

# REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No \_\_\_\_\_

## **SOURCE REMOVAL SUMMARY**

Describe how source is to be removed.

Partially buried produced water vault was removed by Unlimited.

## **REMEDIATION SUMMARY**

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

All results were within Table 910-1 limits. The pit will be backfilled.

## **Soil Remediation Summary**

### In Situ

- \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )
- \_\_\_\_\_ Chemical oxidation
- \_\_\_\_\_ Air sparge / Soil vapor extraction
- \_\_\_\_\_ Natural Attenuation
- \_\_\_\_\_ Other \_\_\_\_\_

### Ex Situ

- \_\_\_\_\_ Excavate and offsite disposal
- \_\_\_\_\_ If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_
- \_\_\_\_\_ Name of Licensed Disposal Facility or COGCC Facility ID # \_\_\_\_\_
- \_\_\_\_\_ Excavate and onsite remediation
- \_\_\_\_\_ Land Treatment
- \_\_\_\_\_ Bioremediation (or enhanced bioremediation)
- \_\_\_\_\_ Chemical oxidation
- \_\_\_\_\_ Other \_\_\_\_\_

## **Groundwater Remediation Summary**

- \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )
- \_\_\_\_\_ Chemical oxidation
- \_\_\_\_\_ Air sparge / Soil vapor extraction
- \_\_\_\_\_ Natural Attenuation
- \_\_\_\_\_ Other \_\_\_\_\_

## **GROUNDWATER MONITORING**

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

## REMEDIATION PROGRESS UPDATE

### PERIODIC REPORTING

Frequency:  Quarterly  Semi-Annually  Annually  Other \_\_\_\_\_

Report Type:  Groundwater Monitoring  Land Treatment Progress Report  O&M Report  
 Other \_\_\_\_\_

### WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? \_\_\_\_\_

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards \_\_\_\_\_

E&P waste (solid) description \_\_\_\_\_

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: \_\_\_\_\_

Volume of E&P Waste (liquid) in barrels \_\_\_\_\_

E&P waste (liquid) description \_\_\_\_\_

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: \_\_\_\_\_

## REMEDIATION COMPLETION REPORT

### REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? Yes \_\_\_\_\_

Do all soils meet Table 910-1 standards? Yes \_\_\_\_\_

Does the previous reply indicate consideration of background concentrations? No \_\_\_\_\_

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? \_\_\_\_\_

Does Groundwater meet Table 910-1 standards? Yes \_\_\_\_\_

Is additional groundwater monitoring to be conducted? No \_\_\_\_\_

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

All results were within Table 910-1 limits. The pit will be backfilled.

Is the described reclamation complete? Yes \_\_\_\_\_

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim?  Final?

Did the Surface Owner approve the seed mix? Yes \_\_\_\_\_

If NO, does the seed mix comply with local soil conservation district recommendations? Yes \_\_\_\_\_

# IMPLEMENTATION SCHEDULE

## **PRIOR DATES**

Date of Surface Owner notification/consultation, if required. \_\_\_\_\_

Actual Spill or Release date, if known. \_\_\_\_\_

## **SITE INVESTIGATION DATES**

Date of Initial Actions described in Site Investigation Plan (start date). 10/02/2019

Date of commencement of Site Investigation. \_\_\_\_\_

Date of completion of Site Investigation. 10/22/2019

## **REMEDIAL ACTION DATES**

Date of commencement of Remediation. \_\_\_\_\_

Date of completion of Remediation. \_\_\_\_\_

## **SITE RECLAMATION DATES**

Date of commencement of Reclamation. \_\_\_\_\_

Date of completion of Reclamation. \_\_\_\_\_

**OPERATOR COMMENT**

This SF27 is for closure of the partially buried produced water vault at this location. All results are within Table 910-1 limits. Figure and lab analytical results are attached to this document.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Dave Castro \_\_\_\_\_

Title: Sr. Env. Specialist \_\_\_\_\_

Submit Date: 10/31/2019 \_\_\_\_\_

Email: dcastro@srcenergy.com \_\_\_\_\_

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Candice (Nikki) Graber \_\_\_\_\_

Date: 10/31/2019 \_\_\_\_\_

Remediation Project Number: 14290 \_\_\_\_\_

**COA Type****Description**

	<p>Based on the information presented, it appears that no further action is necessary at this time and the COGCC approves the closure request. However, should future conditions at the site indicate contaminant concentrations in soils exceeding COGCC standards or if groundwater is found to be impacted, then further investigation and/or remediation activities may be required. In addition, the surface area disturbed by the remediation activity shall be reclaimed in accordance with the 1000 Series Reclamation Rules.</p> <p>For locations with active ongoing oil and gas operations, comply with Rule 1003 interim reclamation requirements and for locations that will no longer have active oil and gas operations, comply with Rule 1004 Final Reclamation requirements.</p>
--	---

**Attachment Check List**

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

**Att Doc Num****Name**

402227394	FORM 27-SUPPLEMENTAL-SUBMITTED
402227419	SOIL SAMPLE LOCATION MAP
402227430	ANALYTICAL RESULTS

Total Attach: 3 Files

**General Comments****User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)