

Inspection Photos

Location Name: North Platte /41-34 Pad

Location #: 413974



Photo #1

North Platte U-Y-34HNB (05-123-36937) Wellsite

Shut-In | SI

.Sign with company & well name NOT posted



Photo #2

North Platte P-T-34HZ, U-Y-34HNB Battery

Shut-down | Inactive