

Inspection Photos
Location Name: North Platte /41-34 Pad
Location #: 413974




Photo #1

North Platte 41-34 (05-123-30518) Wellsite

Temporarily Abandoned | TA



Photo #2

North Platte 42-34 (05-123-35676) Wellsite

Temporarily Abandoned | TA

.Sign with company & well name NOT posted

Inspection Photos
Location Name: North Platte /41-34 Pad
Location #: 413974



Photo #3

North Platte 31-34, 32-34, 41-34, 42-34 Battery

Shut-down | Inactive