

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/30/2019

Submitted Date:

10/31/2019

Document Number:

696101494

**FIELD INSPECTION FORM**Loc ID 413974 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	All Inspections
,		dnr_cogccengineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412522	WELL	TA	04/01/2019	OW	123-30518	NORTH PLATTE 41-34	TA
429081	WELL	SI	04/01/2019	OW	123-35676	North Platte 42-34	TA

**General Comment:**

This is a WELL & BATTERY inspection.  
Well(s): 2 ; Temporarily Abandoned | TA.  
Battery: Shut-down | Inactive

Centralized Battery serves 2 Location IDs (413457, 413974).  
(Well(s): 4 ; 2: Shut-In | SI ; 2:Temporarily Abandoned | TA).  
(1: Other well associated w/ Location ID #413974 is connected to another Battery/Facility.)

Refer to Field Inspection Report Doc. #696101492 and/or Location ID #413457  
for Battery / Facility, Equipment info.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:	Sign with company & well name NOT posted at North Platte 42-34 wellsite. Refer to Rule 210.b. (60 Days). * Post sign with company & well name at North Platte 42-34 wellsite. Comply w/ Rule 210.b. Corrective Action date: 12/30/2019. See photo #2.			
Corrective Action:	* Post sign with company & well name at North Platte 42-34 wellsite. Comply w/ Rule 210.b. See photo #2.			Date: 12/30/2019
Type				
Comment:	Refer to Field Inspection Report Doc. #696101492 and/or Location ID #413457 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	WELLHEAD			
Comment:	2 - Wellsites: Iron panel			
Corrective Action:				Date:
Type				
Comment:	Refer to Field Inspection Report Doc. #696101492 and/or Location ID #413457 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Other	# 2			corrective date
Comment:	2 - Wellsites: w/ Master & casing valves.			
Corrective Action:				Date:
Type: Bradenhead	# 2			
Comment:	2 - Wellsites: Appears plumbed to surface.			

Corrective Action:		Date:	
Type:	#		
Comment:	Refer to Field Inspection Report Doc. #696101492 and/or Location ID #413457 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.363892,-104.413841
Comment:	Centralized Battery serves 2 Location IDs (413457, 413974). Refer to Field Inspection Report Doc. #696101492 and/or Location ID #413457 for Battery / Facility, Equipment info.				
Corrective Action:		Date:			

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 412522 Type: WELL API Number: 123-30518 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA. Observed well disconnected from flowline.  
COGCC records indicate last production: 08/2018.  
Form 5A doc #401901355 indicates TA date: 08/01/2018. Approval PENDING.

Corrective Action:  Date: Facility ID: 429081 Type: WELL API Number: 123-35676 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA. Observed well disconnected from flowline.  
COGCC records indicate last production: 03/2019.

Corrective Action:  Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On WED 10/30/2019 at approximately 16:19 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC  Location Name: North Platte /41-34 Pad  Location ID: 413974  Well Names: North Platte 41-34, North Platte 42-34  API: 05-123-30518, 05-123-35676  Location County: Weld County, Colorado  Weather: Clear w/ prior snow cover</p> <p>While there, I observed:  Well(s): 2 ; Temporarily Abandoned   TA.  Battery: Shut-down   Inactive</p> <p>Centralized Battery serves 2 Location IDs (413457, 413974).  (Well(s): 4 ; 2: Shut-In   SI ; 2:Temporarily Abandoned   TA).  (1: Other well associated w/ Location ID #413974 is connected to another Battery/Facility.)</p> <p>Refer to Field Inspection Report Doc. #696101492 and/or Location ID #413457 for Battery / Facility, Equipment info.</p> <p>During this inspection, the following possible compliance issues were observed:  1.) Sign with company &amp; well name NOT posted at North Platte 42-34 wellsite.  Refer to Rule 210.b. (60 Days).  * Post sign with company &amp; well name at North Platte 42-34 wellsite.  Comply w/ Rule 210.b.  Corrective Action date: 12/30/2019.  See photo #2.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/31/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101495	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4977929">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4977929</a>