

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/01/2019

Submitted Date:

11/01/2019

Document Number:

689703710

**FIELD INSPECTION FORM**

Loc ID 335656 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name      | Phone | Email                                     | Comment                   |
|-------------------|-------|---|---------------------------|
| , Caerus Piceance |       | COGCC.inspections@caerus<br>oilandgas.com | Piceance inspections only |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                 | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------------|-------------|
| 278559      | WELL | PR     | 12/01/2018  | GW         | 045-10895 | N.PARACHUTE WF16D<br>023 596  | PR          |
| 278560      | WELL | PR     | 12/01/2018  | GW         | 045-10894 | N. PARACHUTE WF16B<br>023 596 | PR          |
| 278561      | WELL | SI     | 05/01/2019  | GW         | 045-10893 | N.PARACHUTE WF13D<br>023 596  | SI          |
| 278563      | WELL | PR     | 12/01/2018  | GW         | 045-10892 | N.PARACHUTE WF13B<br>023 596  | PR          |
| 278568      | WELL | PR     | 12/01/2018  | GW         | 045-10891 | N.PARACHUTE WF12B<br>023 596  | PR          |
| 278572      | WELL | PR     | 12/01/2018  | GW         | 045-10890 | N.PARACHUTE WF10D<br>023 596  | PR          |
| 278575      | WELL | PR     | 12/01/2018  | GW         | 045-10889 | N.PARACHUTE WF09D<br>023 596  | PR          |
| 278577      | WELL | PR     | 12/01/2018  | GW         | 045-10888 | N.PARACHUTE WF04B<br>023 596  | PR          |

**General Comment:**

COGCC Inspection Report Summary

On Friday 11-1-19 at approximately 14:00 hours, I, Inspector Mike Longworth, conducted an inspection of CAERUS PICEANCE LLC N.PARACHUTE-65S96W /23SWSE location #335656 in Garfield County, Colorado.

**Location****Lease Road:**

|                   |        |       |  |
|-------------------|--------|-------|--|
| Type              | Access |       |  |
| comment:          |        |       |  |
| Corrective Action |        | Date: |  |

Overall Good: ☒**Signs/Marker:**

|                    |            |       |  |
|--------------------|------------|-------|--|
| Type               | CONTAINERS |       |  |
| Comment:           |            |       |  |
| Corrective Action: |            | Date: |  |
| Type               | WELLHEAD   |       |  |
| Comment:           |            |       |  |
| Corrective Action: |            | Date: |  |
| Type               | BATTERY    |       |  |
| Comment:           |            |       |  |
| Corrective Action: |            | Date: |  |

**Emergency Contact Number:**

|                    |     |             |
|--------------------|-----|-------------|
| Comment:           | 911 |             |
| Corrective Action: |     | Date: _____ |

**Good Housekeeping:**

|                    |       |       |  |
|--------------------|-------|-------|--|
| Type               | TRASH |       |  |
| Comment:           |       |       |  |
| Corrective Action: |       | Date: |  |

Overall Good: ☒**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

|                           |               |       |                 |
|---------------------------|---------------|-------|-----------------|
| Type: Ancillary equipment | # 1           |       | corrective date |
| Comment:                  | Chemical tank |       |                 |
| Corrective Action:        |               | Date: |                 |
| Type: Plunger Lift        | # 8           |       |                 |
| Comment:                  |               |       |                 |
| Corrective Action:        |               | Date: |                 |
| Type: Gas Meter Run       | # 2           |       |                 |
| Comment:                  | Gas lift      |       |                 |
| Corrective Action:        |               | Date: |                 |

|                     |                   |       |  |
|---------------------|-------------------|-------|--|
| Type: Gas Meter Run | # 8               |       |  |
| Comment:            | Production meters |       |  |
| Corrective Action:  |                   | Date: |  |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities  |  |       |      |             |           |           |    |               |    |
|-----------------------|--|-------|------|-------------|-----------|-----------|----|---------------|----|
| Facility ID:          | 278559   | Type: | WELL | API Number: | 045-10895 | Status:   | PR | Insp. Status: | PR |
| <b>Producing Well</b> |  |       |      |             |           |           |    |               |    |
| Comment:              | Producing  |       |      |             |           |           |    |               |    |
| Corrective Action:    |  |       |      |             |           | Date:     |    |               |    |
| Facility ID:          | 278560   | Type: | WELL | API Number: | 045-10894 | Status:   | PR | Insp. Status: | PR |
| <b>Producing Well</b> |  |       |      |             |           |           |    |               |    |
| Comment:              | Producing  |       |      |             |           |           |    |               |    |
| Corrective Action:    |  |       |      |             |           | Date:     |    |               |    |
| Facility ID:          | 278561   | Type: | WELL | API Number: | 045-10893 | Status:   | SI | Insp. Status: | SI |
| <b>Idle Well</b>      |  |       |      |             |           |           |    |               |    |
| Purpose:              | <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned |       |      |             |           | Reminder: |    |               |    |
| Comment:              | Shut in last produced April 2019.  |       |      |             |           |           |    |               |    |
| Corrective Action:    |  |       |      |             |           | Date:     |    |               |    |
| Facility ID:          | 278563   | Type: | WELL | API Number: | 045-10892 | Status:   | PR | Insp. Status: | PR |
| <b>Producing Well</b> |  |       |      |             |           |           |    |               |    |
| Comment:              | Producing  |       |      |             |           |           |    |               |    |
| Corrective Action:    |  |       |      |             |           | Date:     |    |               |    |
| Facility ID:          | 278568   | Type: | WELL | API Number: | 045-10891 | Status:   | PR | Insp. Status: | PR |
| <b>Producing Well</b> |  |       |      |             |           |           |    |               |    |
| Comment:              | Producing  |       |      |             |           |           |    |               |    |
| Corrective Action:    |  |       |      |             |           | Date:     |    |               |    |
| Facility ID:          | 278572   | Type: | WELL | API Number: | 045-10890 | Status:   | PR | Insp. Status: | PR |
| <b>Producing Well</b> |  |       |      |             |           |           |    |               |    |
| Comment:              | Producing  |       |      |             |           |           |    |               |    |
| Corrective Action:    |  |       |      |             |           | Date:     |    |               |    |
| Facility ID:          | 278575   | Type: | WELL | API Number: | 045-10889 | Status:   | PR | Insp. Status: | PR |
| <b>Producing Well</b> |  |       |      |             |           |           |    |               |    |
| Comment:              | Producing  |       |      |             |           |           |    |               |    |
| Corrective Action:    |  |       |      |             |           | Date:     |    |               |    |
| Facility ID:          | 278577   | Type: | WELL | API Number: | 045-10888 | Status:   | PR | Insp. Status: | PR |
| <b>Producing Well</b> |  |       |      |             |           |           |    |               |    |
| Comment:              | Producing  |       |      |             |           |           |    |               |    |
| Corrective Action:    |  |       |      |             |           | Date:     |    |               |    |

|                       |           |       |  |
|-----------------------|-----------|-------|--|
| <b>Producing Well</b> |           |       |  |
| Comment:              | Producing |       |  |
| Corrective Action:    |           | Date: |  |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
|                  |                 | Gravel                  | Pass                  |  |                          |         |
| Ditches          | Pass            |                         |                       |  |                          |         |
|                  |                 |                         |                       | Material Handling And Spill Prevention | Pass                     |         |
|                  |                 | Ditches                 | Pass                  |  |                          |         |
| Berms            | Pass            |                         |                       |  |                          |         |
| Gravel           | Pass            |                         |                       |  |                          |         |
|                  |                 | Compaction              | Pass                  |  |                          |         |
| Compaction       | Pass            |                         |                       |  |                          |         |
|                  |                 | Culverts                | Pass                  |  |                          |         |
|                  |                 | Berms                   | Pass                  |  |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                    | URL   |
|--------------|--------------------------------|---|
| 689703712    | Inspection 689703710 photo log | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4979112">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4979112</a> |