

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/01/2019

Submitted Date:

11/01/2019

Document Number:

689703713

**FIELD INSPECTION FORM**
 Loc ID 335649 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284094	WELL	PR	03/28/2007	GW	045-12076	N. PARACHUTE WF03D K25A 596	PR
284095	WELL	PR	04/05/2006	GW	045-12075	N.PARACHUTE WF 14D K25A 596	PR
284096	WELL	PR	04/09/2008	GW	045-12074	N. PARACHUTE WF06C K25A 596	PR
284097	WELL	PR	04/05/2006	GW	045-12073	N.PARACHUTE WF03B K25A 596	PR
284098	WELL	PR	04/05/2006	GW	045-12072	N.PARACHUTE WF06B K25A 596	PR
284099	WELL	PR	02/01/2018	GW	045-12071	N. PARACHUTE WF02D K25A 596	PR
284100	WELL	PR	04/05/2006	GW	045-12070	N.PARACHUTE WF 14B K25A 596	PR
284101	WELL	PR	04/05/2006	GW	045-12069	N.PARACHUTE WF04D K25A 596	PR

**General Comment:**

COGCC Inspection Report Summary

 On Friday 11-1-19 at approximately 15:00 hours, I, Inspector Mike Longworth, conducted an inspection at CAERUS PICEANCE LLC N.  
PARACHUTE-65S96W /25NESW Location # 335649.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment: Gas lift			
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment: Production meters			
Corrective Action:		Date:	

Type: Ancillary equipment	# 2		
Comment:	Chemical tanks		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	284094	Type:	WELL	API Number:	045-12076	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	284095	Type:	WELL	API Number:	045-12075	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	284096	Type:	WELL	API Number:	045-12074	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	284097	Type:	WELL	API Number:	045-12073	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	284098	Type:	WELL	API Number:	045-12072	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	284099	Type:	WELL	API Number:	045-12071	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	284100	Type:	WELL	API Number:	045-12070	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	284101	Type:	WELL	API Number:	045-12069	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Ditches	Pass					
Gravel	Pass					
		Berms	Pass			
		Ditches	Pass			
		Culverts	Pass			
		Gravel	Pass			
Berms	Pass					
				Material Handling And Spill Prevention	Pass	
		Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689703714	Inspection 689703713 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4979113">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4979113</a>