

Inspection Photos
Location Name: Pappenheim 2-32 Battery
Location ID: 322676



Photo 1: Tank Battery Sign



Photo 2: Tank Battery

Inspection Photos
Location Name: Pappenheim 2-32 Battery
Location ID: 322676



Photo 3: Weeds removed



Photo 4: Weeds removed, hole repaired

Inspection Photos
Location Name: Pappenheim 2-32 Battery
Location ID: 322676



Colorado Oil and Gas Conservation Commission
40.534, -104.67809, 1451.8m, 200°
Oct 31, 2019 11:29:02

Photo 5: Hole repaired



Colorado Oil and Gas Conservation Commission
40.53419, -104.6781, 1448.3m, 17°
Oct 31, 2019 11:19:53

Photo 6: Unused equipment removed