

Inspection Photos
Operator: BP America
Location/API #: 067-09562
Date: 10-24-2019



Photo 1. View of the project area from the well entrance facing center.



Photo 2. View of the plugged well marker facing northeastward. Area is infested with musk thistles, and revegetation is sparse in this area.



Photo 3. View of reference are vegetation comprised of mixed pinyon juniper woodland, and sagebrush shrubland with largely native grasses such as James galleta and forbs such as perky Sue.