


**LEGEND**

- ✕ RELEASE LOCATION
- ⊗ MONITORING WELL
- ⊗ DESTROYED MONITORING WELL
- FORMER WELLHEAD
- M FORMER METER HOUSE
- RELATIVE GROUNDWATER ELEVATION CONTOUR  
CONTOUR INTERVAL = 0.50 FEET  
GRADIENT = 0.006 FEET/FOOT
- FLOW LINE
- - - IRRIGATION DITCH
- GAS — GAS GATHERING LINE
- x — x FORMER FENCE
- EXCAVATION EXTENT
- FORMER BERM

GROUNDWATER ELEVATIONS WERE MEASURED ON SEPTEMBER 17, 2019.  
NM: NOT MEASURED

IMAGE COURTESY OF GOOGLE EARTH 2015



**FIGURE 2**  
**GROUNDWATER ELEVATION CONTOUR MAP**  
 HSR-DREYER 5-5  
 SWNW SEC 5-T1S-R65W  
 ADAMS COUNTY, COLORADO  
 KERR-MCGEE OIL & GAS ONSHORE, LP

