

Inspection Photos

Loc#433706

Operator: Caerus

Inspection Number: 692401533

Inspection Date: 11/1/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry to Northwest.

November 1, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Rose K22W Loc#433706



Photo#2:
Overview of Location to Southeast.

November 1, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Rose K22W Loc#433706



Photo#3:
One of several Russian olive trees on site.



Photo#4:
Cheat grass established on South berm.

November 1, 2019