

Inspection Photos
Operator: Logos Operating
Location/API #: 067-05588
Date: 10-24-2019



Photo 1. View of the project area from the western edge facing center. Portions of the well pad are infested with kochia weeds growing up to 4 feet tall.



Photo 2. View of the western revegetation area from the northwestern access facing southward. Some desirable vegetation is becoming established, although location is infested with tall kochia weeds and debris.



Photo 3. View of sediment deposition at the toe of the eastern cut-slope.



Photo 4. View of bare and eroding soils on the well pad cut slope.



Photo 5. View of reference are vegetation comprised of mixed pinyon juniper woodland, and sagebrush shrubland with native grasses such as James galleta and forbs such as *Tetaneuris* sp.