

Inspection Photos
Operator: Logos Operating
Location/API #: 067-08102
Date: 10-24-2019



Photo 1. View of the project area from the southern edge facing center.



Photo 2. View of the southern project area from the southeastern edge facing westward. Revegetation is progressing with western wheatgrass and sand dropseed. Blue arrow points to Scotch thistles in the southern project area. Approximately 100 individuals observed.



Photo 3. View of reference are vegetation comprised of mixed pinyon juniper woodland, and sagebrush shrubland with native grasses such as James galleta and forbs such as *Tetaneuris* sp.