

Inspection Photos  
Operator: BP America  
Location/API #: 067-08496  
Date: 10-24-2019



Photo 1. View of the project area from the eastern corner facing center.





Photo 2. View of the southeastern fill slope from the eastern edge facing southwestward. Interim reclamation area is infested with musk and Scotch thistles. Approximately 2000 individuals observed.





Photo 3. View of erosional channel approximately 2 feet wide and 1 foot deep, forming within the eastern project area.





Photo 4. View of reference are vegetation comprised of mixed pinyon juniper woodland, and sagebrush shrubland with native grasses such as James galleta and forbs such as *Tetrandeum* sp.