

Inspection Photos

Location Name: MOSSBERG PMJ-65N66W /30NWSE

Location #: 326979



Photo #1

Mossberg PMJ 30-10 (05-123-13965) Wellsite

Plugged & Abandoned | PA

Unused Equipment

prior insp.



Photo #2

Mossberg PMJ 30-10 Wellsite

Plugged & Abandoned | PA

Unused equipment appears removed

Reclamation progressing

~ 145 yds.

Inspection Photos

Location Name: MOSSBERG PMJ-65N66W /30NWSE

Location #: 326979



Photo #3
Mossberg-PM J30-9, Mossberg PMJ 30-10 Battery
Unused Equipment
Gas Meter run riser
prior insp.



Photo #4
Mossberg-PM J30-9, Mossberg PMJ 30-10 Battery
Abandoned | All equipment appears removed
Reclamation progressing