

Inspection Photos
Location Name: LDS A 9, 16, 20-8 Tank Battery
Facility ID: 466250



Photo #1 picture taken on the north side, Berm wall is Mangled up. 9/23/19



Photo #2 picture taken on the north side, Berm wall is Mangled up. 11/5/19

Inspection Photos
Location Name: LDS A 9, 16, 20-8 Tank Battery
Facility ID: 466250



Photo #3 Picture taken from the SE corner, Berm wall is Mangled up. On 9/23/19



Photo #4 Picture taken from the SE corner, Berm wall is Mangled up. On 11/5/19