

Inspection Photos
Location Name: Johnson 29-13
API ID: 123-20444



Photo #1 Wellhead, Sign, & Weeds on 10/9/19



Photo #2 Wellhead, Sign, & Weeds on 11/5/19

Inspection Photos
Location Name: Johnson 29-13
API ID: 123-20444



Photo #3 Yellow "LTSI" Variance tag & Weeds on 10/9/19



Photo #4 Yellow "LTSI" Variance tag & Weeds on 11/5/19