

Inspection Photos  
Location Name: Jilson #3  
Location ID: 336406



Photo #1 WH sign



Photo #2 Horses head on ground

**Inspection Photos**  
**Location Name: Jilson #3**  
**Location ID: 336406**



**Photo #3 weeds appear to have been cut on location**

**Photo #4 flow lines are disconnected from WH**

**Inspection Photos**  
**Location Name: Jilson #3**  
**Location ID: 336406**



**Photo #5 PU motor missing**