

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/04/2019

Submitted Date:

11/04/2019

Document Number:

697000156

**FIELD INSPECTION FORM**

Loc ID 321550 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 61250  
Name of Operator: MULL DRILLING COMPANY INC  
Address: 1700 N WATERFRONT PKWY B#1200  
City: WICHITA State: KS Zip: 67206-

**Findings:**

- 11 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Akers, Tracy		takers@mulldrilling.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207174	WELL	PR	12/13/1971	OW	017-06109	KLEPPER 2	PR

**General Comment:**

[Routine Inspection](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road through farm ground		
Corrective Action:		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Metal signs by tank		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lease sign by tank battery		
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: FWKO	# 1		
Comment:	FWKO in west metal shed		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Electric panel, cathodic rectifier and propane tank at tank battery		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Bethlehem 160		
Corrective Action:		Date:	

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		38.879370,-102.358600
Comment: Central tank battery for Klepper 1, 2, 4					
Corrective Action:					Date:
<b>Paint</b>					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**

Facility ID: 207174 Type: WELL API Number: 017-06109 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Central tank battery for \(Klepper 1,2,4\)](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT