

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/05/2019

Submitted Date:

11/05/2019

Document Number:

697000159

FIELD INSPECTION FORM

Loc ID 321556 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 61250
Name of Operator: MULL DRILLING COMPANY INC
Address: 1700 N WATERFRONT PKWY B#1200
City: WICHITA State: KS Zip: 67206-

Findings:

12 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Akers, Tracy	719-342-1813	takers@mulldrilling.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207205	WELL	PR	02/28/1974	OW	017-06140	CHAMPLIN-HORBOSTAL 1	PR

General Comment:

[Routine Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Gravel road through CRP		
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:	Stickers on chemical tank		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Lease sign at tank battery		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Metal signs by tanks		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:			Date:

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:	CMI 456		
Corrective Action:			Date:
Type: FWKO	# 1		
Comment:	FWKO on east side of tanks		
Corrective Action:			Date:
Type: Ancillary equipment	# 4		
Comment:	Electric panel, cathodic rectifier, chemical tank w/containment, transformer on east side of location		
Corrective Action:			Date:
Type: Prime Mover	# 1		

Comment:	Electric motor		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		38.875610,-102.348580
Comment:	Tank battery is 1100' west of wellhead				
Corrective Action:		Date:			

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 207205 Type: WELL API Number: 017-06140 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Tank battery is 1100' W @ 38.875610/-102.348580](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT