

Inspection Photos
Location Name: Great Western Pad 7
Location ID: 333027



Photo 1: Wellhead Sign



Photo 2: Wellhead

Inspection Photos
Location Name: Great Western Pad 7
Location ID: 333027



Photo 3: Stained soil



Photo 4: Stained soil (zoomed in)

Inspection Photos
Location Name: Great Western Pad 7
Location ID: 333027



Photo 5: Tank Battery Sign



Photo 6: Tank Battery/ inadequate berm (earth)

Inspection Photos
Location Name: Great Western Pad 7
Location ID: 333027



Photo 7: Separator NOT anchored



Photo 8: BBLs faded/ No NFPA placard

Inspection Photos
Location Name: Great Western Pad 7
Location ID: 333027



Photo 9: Tanks anchored



Photo 10: Tank anchored

Inspection Photos
Location Name: Great Western Pad 7
Location ID: 333027



Photo 11: Tank anchored