

Inspection Photos
Location Name: Great Western Pad 8
Location ID: 333026



Colorado Oil and Gas Conservation Commission
40.45485, -104.87381, 1430.2m, 37°
Nov 5, 2019 12:42:28

Photo 1: Wellhead Sign



Colorado Oil and Gas Conservation Commission
40.45486, -104.87382, 1430.2m, 44°
Nov 5, 2019 12:42:34

Photo 2: Wellhead

Inspection Photos
Location Name: Great Western Pad 6
Location ID: 333026



Photo 3: Birds nest removed



Photo 4: Stained soil

Inspection Photos
Location Name: Great Western Pad 6
Location ID: 333026



Photo 5: Wellhead Sign



Photo 6: Wellhead

Inspection Photos
Location Name: Great Western Pad 6
Location ID: 333026



Photo 7: Stained soil



Photo 8: Stained soil (Different Angle)

Inspection Photos
Location Name: Great Western Pad 6
Location ID: 333026



Photo 9: Tank Battery Sign



Photo 10: Tank Battery

Inspection Photos
Location Name: Great Western Pad 6
Location ID: 333026



Photo 11: No NFPA placard on h2o tank